



Sơ đồ máy GWS 6-100S

STT	Mã sản phẩm	Tên sản phẩm
1	1 619 P10 030	Motor Housing .
2	1 619 P08 322	Field 230V .
3	1 619 P08 222	Armature 220V .
5	1 606 610 141	Fan .
4	1 619 P09 984	Switch .
5	1 619 P10 097	Power supply cord .
6	2 600 703 012	Grommet Ø6,5-Ø6,9x95 MM .
7	1 601 302 017	Fastening Clamp .
13	1 619 P11 239	Deep-Groove Ball Bearing .
14	2 609 110 094	Deep-Groove Ball Bearing .
16	1 604 336 035	Brush Holder .
17	1 604 652 013	Spiral Spring .
24	1 619 P10 033	Switch Support .
25	1 619 P10 031	Housing Cover .
26	1 600 502 024	Intermediate Ring .
27	1 600 206 025	Rubber Ring .
29	1 600 591 023	Air-Deflector Ring .
30	1 600 591 024	Air-Deflector Ring .
32	1 603 523 111	Grinding Spindle M10, SW12 .
33	1 600 210 041	O-Ring 42,0x1,1 MM .
37	1 600 100 033	Cover Disc .
38	1 619 P01 991	Bevel Gear .
39	1 619 P01 990	Pinion .
45	2 915 011 007	Hex Nut DIN 934-M6-8-A .
47	2 609 110 052	Special Screw .
48	1 619 P00 220	Torx Oval-Head Screw 3x10 .
49	1 603 435 068	Thread-forming tap. Screw DIN 7500, M4x10, SR10.2 .
50	2 910 611 020	Tapping Screw DIN 7981-ST3,9x19-C-H .
55	2 910 611 022	Tapping Screw DIN 7981-ST3,9x25-C-H .
80	3 600 150 021	Sealing disk .
650/10	2 602 025 067	Auxiliary Handle M10, Ø32,5x105 MM .
650/20	1 619 P09 976	Round Nut With 2 Holes .

Sơ đồ máy GWS 6-100S

650/30	1 619 P08 928	Pin-Type Face-Wrench .
650/50	1 605 703 113	Clamping-Flange M10, 16-20 MM .
810	1 619 P11 715	Carbon-Brush Set .
821	1 605 806 466	Gear Housing .
828	1 619 P10 716	Bearing Flange .
840	1 607 000 298	Push-Button BLACK
841	1 600 910 018	Needle bearing Ø8xØ12x8 MM .
850	1 619 P01 321	Protective Cover .

0 601 375 0AB
Stand } 13-12-16
Issue }

Fig. /Abb. 1

Gerad - Verzahnung

● Vor Demontage des Ankers
Kohlebürsten 5mm zurückziehen !
Before the armature is removed the carbon brushes
must be withdrawn by at least 5mm !

