



Sơ đồ máy GWS7-100T

STT	Mã sản phẩm	Tên sản phẩm
1	1 619 P10 070	Motor Housing .
3	1 619 P05 210	Armature 220-230V .
5	1 619 P02 801	Fan .
4	1 607 200 179	Switch .
6	2 600 703 012	Grommet Ø6,5-Ø6,9x95 MM .
7	1 601 302 017	Fastening Clamp .
9	1 619 P02 882	Manufacturer's nameplate GWS 7-100 T .
13	1 619 P00 456	Ball Bearing 7x19x6 MM .
14	1 619 P00 455	Ball Bearing .
16	1 619 P02 845	Brush Holder .
16/21	1 619 P02 809	Spiral Spring .
18	1 604 611 031	Compression Spring .
22	1 619 P02 811	Adjusting Slide .
23	1 619 P09 290	Switch Button .
24	1 619 P02 828	Brush-Cover .
25	1 619 P02 844	Housing Cover .
26	1 600 502 023	Intermediate Ring .
27	1 600 206 025	Rubber Ring .
28/1	1 619 P07 440	Ball Bearing .
28/3	2 916 660 013	Spring retaining ring DIN 472-32x1,2 MM .
29	1 619 P02 818	Air-Deflector Ring .
30	1 619 P02 819	Air Distributor .
32	1 603 523 111	Grinding Spindle M10, SW12 .
33	1 619 P02 820	O-Ring 44,0x1,0 MM .
35	1 619 P02 821	Shim 0,1 MM .
35	1 619 P02 822	Shim 0,2 MM .
36	1 619 P00 987	Washer .
37	1 600 100 033	Cover Disc .
38	1 619 P02 824	Conversion Gear .
39	1 619 P02 826	Pinion .



Sơ đồ máy GWS7-100T


45	2 915 011 007	Hex Nut DIN 934-M6-8-A .
47	2 609 110 052	Special Screw .
48	1 619 P02 849	Torx Oval-Head Screw 3x8 .
49	1 603 435 068	Thread-forming tap. Screw DIN 7500, M4x10, SR10.2 .
50	1 619 P00 105	Torx Oval-Head Screw 4x20 .
55	1 619 P01 066	Torx Oval-Head Screw 4x25 .
57	1 619 P02 848	Torx Oval-Head Screw 4x12 .
80	3 600 150 021	Sealing disk .
131	1 619 P01 598	Hex Screw Driver 4x95 .
132	1 619 P06 843	Key Holder .
650/10	2 602 025 067	Auxiliary Handle M10, Ø32,5x105 MM .
650/20	1 619 P09 976	Round Nut With 2 Holes .
650/30	2 609 110 015	Pin-Type Face-Wrench .
650/50	1 605 703 113	Clamping-Flange M10, 16-20 MM .
651	1 619 P02 831	Protective Cover Ø100 MM GRAY
802	1 619 P07 239	Field 220-230V .
805	1 607 000 387	Power supply cord .
808	1 619 P02 911	Nameplate .
810	1 619 P02 870	Carbon-Brush Set .
823	1 619 P10 838	Switch Button .
828	1 619 P07 451	Bearing Flange .
831	1 619 P07 276	Gear Housing .
840	1 619 P02 873	Push-Button .
841	1 600 910 018	Needle bearing Ø8xØ12x8 MM .
858	2 910 641 081	Oval-Head Screw DIN7985-M3,5x5-4.8-H .
894	1 615 430 020	Grease Tube 225 ML .
895	1 605 430 003	Grease Tube 225 ML .

Sơ đồ máy GWS7-100T

3 601 C88 6K0
 Stand | 09-07-01
 Issue | 09-07-13

Fig./Abb. 1

Schräg - Verzahnung



● Vor Demontage des Ankers
 Kohlebürsten 5mm zurückziehen !
 Before the armature is removed the carbon brushes

Änderungen vorbehalten
 Modifications reserved